

File's requirements for the calculation and production of your order.

To get a correct and accurate estimate for your request, please send us only vector files (in the CDR or PDF format - each element of sign should be in vector graphics! )

**!** Files sent as whole pictures in the JPEG, PNG, TIF or etc formats - are not suitable for calculating prices and sign production.

The file should contain all the main parameters of the sign - the basic dimensions (at the extreme points - the width and height in millimeters), the color or colors of each element, the desired materials and type of sign.

## Sample below:

Profile 1 Aluminium boxletters | Depth 30 mm



Before starting production, please: carefully read the estimate, check all sizes, parameters and colors of the product, check the declared materials indicated in our estimate. Make corrections if necessary and let us know if you find any inaccuracies or changes.

**!** After the start of manufacturing (most often), we will not be able to change anything without significant material costs.